





EXISTING CONDITIONS

91 NEWBURY STREET FACADE



1 Existing Elevation
1/2" = 1'-0"




2 Demolition Elevation
1/2" = 1'-0"

remove existing storefront glazing and framing.

remove and salvage decorative wrought iron grill work for re-installation


remove and salvage marble for reuse

remove existing storefront glazing and framing.



1 Existing Elevation
XC8.0 1/2" = 1'-0"

NEW WOODEN FRAMING
PAINTED BLACK TO MATCH
EXISTING



1 Proposed Elevation
XC8.0 1/2" = 1'-0"

Re-install original wrought iron grill work - repaint as required

AREA FOR TENANT SIGNAGE
VINYL APPLIED OR APPLIED METAL LETTERS TO GLAZING.
TENANT COPY/ LOGO/COLOR TO BE PER SEPARATE SUBMISSION BY FUTURE TENANT

Bronze verticle pulls

New copper sill flashing
replace marble sill

NEW BUTT GLAZED STOREFRONT AND DOORS WITH BRONZE HARDWARE

replace existing marble at base - cut to fit new condition



91 NEWBURY STREET FACADE