

All 4th floor
windows have
separated
aluminum
mullions



North side
Facing
Pinckney St

N4-A

N4-B

N4-C

N4-D

N3-A

N3-B

N3-C

N3-D

N2-A

N2-B

N2-C

N2-D

N1-A

N1-B

NB-A

NB-B




Severe rot



S-1B


N-3A





* Broken wood sash

N-1A

A photograph showing a window with a broken sash. The window is set in a brick wall. The sash is broken and wedged, and the weights and ropes are missing. The window is labeled 'W-1A'. The text 'Missing weights and ropes' is overlaid on the upper part of the window. The text 'Sash broken and wedged' is overlaid on the lower part of the window. The window is labeled 'W-1A' on the left side. The window is set in a brick wall. The sash is broken and wedged, and the weights and ropes are missing. The window is labeled 'W-1A'.

Missing
weights
and
ropes

W-1A

Sash
broken
and
wedged



West
side

W-4A

W-3A

W-2A

W-1A

W-BA

W-BB

South facing

S-4A

S-4B

S-3A

S-3B

S-2A


S-2B

S-2C

S-1A

S-1B



A close-up photograph of a metal door or panel assembly. A vertical metal rod or bolt is visible on the left side, extending from the top to the bottom. The metal surface is dark and shows signs of wear, including scratches and some discoloration. At the bottom, the metal assembly is mounted on a concrete base. The concrete is light-colored and appears to be part of a larger structure. The overall scene suggests a heavy-duty door or panel that has been secured with a rod to prevent rattling.

* nailed shut to prevent rattling

S-2B