




116 CHANDLER ST

BOSTON, MA

01/22/2020




EMBARC





PROPERTY LINE

PROPERTY LINE



PATCH AND REPAIR EXISTING ROOF, AS REQUIRED.

REPAIR AND REPOINT EXISTING CORNICE AS REQUIRED.

NEW WOOD 2-OVER-2 WINDOWS IN EXISTING OPENINGS, TYPICAL. PAINT BLACK


REPAIR AND REPOINT EXISTING BRICK MASONRY FACADES ONLY AS REQUIRED.


REPAIR AND RESTORE EXISTING EXTERIOR DOOR.

REPAIR AND RESTORE EXISTING WINDOW SILLS AND HEADERS AS REQUIRED.

REPAIR AND RESTORE EXISTING STOOP AS REQUIRED.













1C



1C

TYPICAL OF 1B, 1C



2C



2C

TYPICAL OF 2A, 2B, 2C



1B



1B

TYPICAL OF 1B, 1C



2A

TYPICAL OF 2A, 2B, 2C



2B



3B



3C



4C



4D



3A



3A

TYPICAL OF 3A, 3B, 3C



4A




4B

TYPICAL OF 4A, 4B, 4C, 4D



NOTE: GARDEN LEVEL WINDOWS NOT SHOWN BEYOND FENCE.



1E



1F



1G



2E



2G



3E



3G



4F

TYPICAL OF 3E, 3F, 3G



2F



2G



3F





4E




4G


TYPICAL OF 2E, 2F, 2G




2 LOWER JAMBS
6" = 1'-0"




3 VENT HEAD
6" = 1'-0"




4 UPPER JAMBS
6" = 1'-0"





5 VENT SILL
6" = 1'-0"




6 CHECK RAIL
6" = 1'-0"




7 GLAZE GRILLES
12" = 1'-0"




1 VENT HEAD - DOOR
6" = 1'-0"



2 LOCK JAMB
6" = 1'-0"



3 HINGE JAMB
6" = 1'-0"



4 GLAZE GRILLES
12" = 1'-0"