


23 UPTON STREET RESTORATION

01-19-21

PREPARED FOR SOUTH END LANDMARK DISTRICT COMMISSION



WINDOW 204 - GARDEN LEVEL



EXTERIOR



INTERIOR

WINDOW 204 - GARDEN LEVEL - SUPPORTING DOCUMENTATION



LOWER SASH



LOWER SASH




UPPER SASH



SILL




JAMB



ADDITIONAL

WINDOW 205 - GARDEN LEVEL



EXTERIOR



INTERIOR


WINDOW 205 - GARDEN LEVEL - SUPPORTING DOCUMENTATION



LOWER SASH



UPPER SASH



JAMB



SILL




GLASS



ADDITIONAL

WINDOW 206 - GARDEN LEVEL



EXTERIOR



INTERIOR

WINDOW 206 - GARDEN LEVEL - SUPPORTING DOCUMENTATION



SILL




JAMB



HEAD

WINDOW 304 - SECOND FLOOR



EXTERIOR



INTERIOR



WINDOW 304 - SECOND FLOOR - SUPPORTING DOCUMENTATION



LOWER SASH



UPPER SASH



JAMB



SILL




GLASS



ADDITIONAL

WINDOW 305 - SECOND FLOOR



EXTERIOR



INTERIOR

WINDOW 305 - SECOND FLOOR - SUPPORTING DOCUMENTATION



LOWER SASH



UPPER SASH



JAMB



SILL





GLASS



ADDITIONAL

WINDOW 404 - THIRD FLOOR - DESCRIPTION



EXTERIOR



INTERIOR

WINDOW 404 - THIRD FLOOR - SUPPORTING DOCUMENTATION



LOWER SASH



UPPER SASH



JAMB



SILL




GLASS



ADDITIONAL

WINDOW 405 - THIRD FLOOR - DESCRIPTION



EXTERIOR



INTERIOR

WINDOW 405 - THIRD FLOOR - SUPPORTING DOCUMENTATION



LOWER SASH



UPPER SASH



JAMB



SILL




GLASS



ADDITIONAL

WINDOW 406 - THIRD FLOOR



EXTERIOR



INTERIOR



WINDOW 406 - THIRD FLOOR - SUPPORTING DOCUMENTATION



UPPER SASH



UPPER SASH




JAMB



SILL



GLASS



ADDITIONAL

ENTRY DOOR - GARDEN LEVEL



EXTERIOR



INTERIOR

ENTRY DOOR - GARDEN LEVEL - SUPPORTING DOCUMENTATION



BOTTOM LEFT



TOP LEFT



MAIL SLOT



ADDITIONAL