



<u>DETAIL A</u> - EXISTING WINDOW BRICK MOLD AT JAMB / HEAD




 $\frac{\mathsf{DETAIL}\;\mathsf{E}}{\mathsf{AT}\;\mathsf{JAMB}}\;\mathsf{-}\;\mathsf{EXISTING}\;\mathsf{WINDOW}\;\mathsf{BRICK}\;\mathsf{MOLD}$



<u>DETAIL B</u> - PROPOSED WINDOW BRICK MOLD AT JAMB / HEAD




<u>DETAIL F</u> - PROPOSED WINDOW BRICK MOLD AT JAMB / HEAD



<u>DETAIL C</u> - EXISTING WINDOW BRICK MOLD AT JAMB / SILL



<u>DETAIL D</u> - PROPOSED WINDOW BRICK MOLD AT JAMB / SILL NOTE: SILL PANNING DETAIL MATCHES HISTORIC PHOTOGRAPH





HISTORIC SILL PANNING. NEW ALUMINUM WINDOW TO MATCH. SEE DETAIL D