



Foxboro, Ma
508-543-5644



Wellesley, Ma
781-239-1068

Fall River, Ma
508-679-4732

Providence, RI
401-273-8733



Marshfield, MA
781-837-4111

To Whom It May Concern,

After conducting a thorough assessment of the two Norway maple (*Acer platanoides*) trees located at the front of your property near the retaining wall, I have determined that their removal is necessary.

The primary concern is the pressure these trees are exerting on the retaining wall due to their root systems. Over time, the expansive root growth of the Norway maples has caused displacement and stress on the wall's structure, compromising its integrity. If left unaddressed, this could lead to further damage, including potential failure of the wall, posing safety risks and increasing repair costs.

While these trees currently appear to be in good health, their root systems are inherently invasive, and removal is the most practical solution to protect the retaining wall and surrounding structures.

I recommend removing these trees because if they are left and the wall is replaced this same damage will happen again in the future. If you wish to discuss replacement options with less invasive species, I would be happy to help.

Please feel free to contact me at 508-838-1003 or CTaylor@treetechinc.net with any questions or concerns.

Carl Taylor
ISA #NE-7058A
TRAQ
RILA #330
Tree Tech Inc

Carl Taylor
ISA & TRAQ # NE-7058A
RILA #330
Tree Tech inc.