

HAVAS + ARNOLD

Exterior Signage 5 Necco Street Boston, MA

Gensler

One Beacon Street Third Floor Boston, Massachusetts 02108

NOTES:


ALL SITE CONDITIONS, LOCATION AND DIMENSIONS MUST BE VERIFIED BY THE CONTRACTOR/INSTALLER PRIOR TO FABRICATION.


MATERIAL, FINISH AND COLOR SAMPLES MUST BE PROVIDED FOR GENSLER'S REVIEW AND APPROVAL UPON REQUEST PRIOR TO FABRICATION, UNLESS OTHERWISE

SHOP DRAWINGS MUST BE PROVIDED TO GENSLER FOR REVIEW PRIOR TO FABRICATION, UNLESS OTHERWISE

Description

	2 cscpc.o			
y 18, 2025	Updated Renderings			
rch 20, 2025	Additional Signage			
ov 4, 2024	BID Documents			
sign Intent Drawings				
VAS ARNOLD)			
oject Number				
7932.700				
escription				
e Page Title				





Detail

Scale: 3/4" = 1' - 0"

A.

OPTION 1:

HAND PAINTED AND DISTRESSED LOGO APPLIED TO BRICK SURFACE.

OPTION 2:

CONTOUR CUT OPTICALLY CLEAR ROUGH WRAP OR VENDOR EQUIVALENT WITH A MATTE OVERLAM TO MATCH WHITE APPLIED DIRECTLY TO WALL SURFACE; CLEAN OF ANY DEBRIS AND BUBBLES.

NOTE:

SIGN FABRICATOR TO VERIFY ALL AS-BUILT CONDITIONS ON SITE SURVEY.

ELECTRONIC ELEVATIONS (PDF FILES) OF AS-BUILT CONDITIONS TO BE PROVIDED TO GENSLER FOR FINAL ARTWORK PREPARATION WHERE APPLICABLE.

FINAL ART FILES TO BE PROVIDED BY GENSLER

SIGN FABRICATOR TO COORDINATE ALL INSTALL REQUIREMENTS WITH GENERAL CONTRACTOR ON SITE PRIOR TO FABRICATION

HAVAS + ARNOLD

Exterior Signage 5 Necco Street Boston, MA

Gensler

One Beacon Street Third Floor Boston, Massachusetts 02108

NOTES:

ALL SITE CONDITIONS, LOCATION AND DIMENSIONS MUST BE VERIFIED BY THE CONTRACTOR/INSTALLER PRIOR TO FABRICATION.

MATERIAL, FINISH AND COLOR SAMPLES MUST BE PROVIDED FOR GENSLER'S REVIEW AND APPROVAL UPON REQUEST PRIOR TO FABRICATION, UNLESS OTHERWISE SPECIFIED

SHOP DRAWINGS MUST BE PROVIDED TO GENSLER FOR REVIEW PRIOR TO FABRICATION, UNLESS OTHERWISE SPECIFIED.

Date	Description	
July 18, 2025	Updated Renderings	
March 20, 2025	Additional Signage	
Nov 4, 2024	BID Documents	
ı		
Design Intent Drawings		
HAVAS ARNOLD		
Project Number		
11.7932.700		
Description		

See Page Title

Scale

As Noted

DI.14


VERITCAL SIGN RENDERS

RENDERS ARE FOR ILLUSTRATIVE REFERENCE ONLY.











LOCATION 2



LOCATION 3

HAVAS + ARNOLD

Exterior Signage 5 Necco Street Boston, MA

Gensler

One Beacon Street Third Floor Boston, Massachusetts 02108

NOTES:

ALL SITE CONDITIONS, LOCATION AND DIMENSIONS MUST BE VERIFIED BY THE CONTRACTOR/INSTALLER PRIOR TO FABRICATION.

MATERIAL, FINISH AND COLOR SAMPLES MUST BE PROVIDED FOR GENSLER'S REVIEW AND APPROVAL UPON REQUEST PRIOR TO FABRICATION, UNLESS OTHERWISE

SHOP DRAWINGS MUST BE PROVIDED TO GENSLER FOR REVIEW PRIOR TO FABRICATION, UNLESS OTHERWISE

Date	Description
July 18, 2025	Updated Renderings
March 20, 2025	Additional Signage
Nov 4, 2024	BID Documents
	·

Design Intent Drawings

HAVAS ARNOLD

Project Number

11.7932.700

Description


See Page Title

Scale

As Noted

DI.15

North Facade Vertical Sign



HAVAS + ARNOLD

Exterior Signage 5 Necco Street Boston, MA

Gensler

One Beacon Street Third Floor Boston, Massachusetts 02108

NOTES:

ALL SITE CONDITIONS, LOCATION AND DIMENSIONS MUST BE VERIFIED BY THE CONTRACTOR/INSTALLER PRIOR TO FABRICATION.

MATERIAL, FINISH AND COLOR SAMPLES
MUST BE PROVIDED FOR GENSLER'S REVIEW
AND APPROVAL UPON REQUEST PRIOR
TO FABRICATION, UNLESS OTHERWISE
SPECIFIED.

SHOP DRAWINGS MUST BE PROVIDED TO GENSLER FOR REVIEW PRIOR TO FABRICATION, UNLESS OTHERWISE SPECIFIED.

Date	Description
July 18, 2025	Updated Renderings
March 20, 2025	Additional Signage
Nov 4, 2024	BID Documents

Design Intent Drawings

HAVAS ARNOLD

Project Number

11.7932.700

Description

See Page Title

Scale

As Noted

DI.II

We were inspired by the historical branding of this building when designing both the exterior branding and some of the interior features. You can see the old logo painted faintly in the below picture. The client was very much interested in having the designs appear as though they had 'always been there.'



Our installers recommend an approach depicted in the left image, which has the logo looking faded and broken-in from day one. We will maintain the ability to return the brick to its original condition.

We proposed two options for application of signage:

Option 1 Vinyl application. This can be easily removed with heat and manual labor without any damage to the existing brick.

Option 2 Paint application as depicted below. The below sample was created by the vendor who would do the paint installation. The paint would be removed with a brick friendly solvent.

