


56 Clarendon St – Cross Street Chandler St View



Failing Doors and Side lites – Structure built in 1997



French Doors and Side Light Eagan Residence 56 Clarendon Street #4, Boston, MA 02116 Landmark District Submittal

04 August 2020



Exterior deterioration – water leaking and door swelling




Interior Deterioration – water leaking and door swelling

BRADFIELD

French Doors and Side Light Eagan Residence 56 Clarendon Street #4, Boston, MA 02116 Landmark District Submittal

04 August 2020



Existing Door set and new Set Drawings

BRADFIELD

INTERIOR DESIGN

French Doors and Side Light Eagan Residence 56 Clarendon Street #4, Boston, MA 02116 Landmark District Submittal

04 August 2020