



STEEL LINTEL AT WINDOW IS RUST JACKING THE MASONRY, OPENING THE BUILDING FACADE FOR WATER AND FREEZE THAW DAMAGE.



FAILED SEALANT JOINT, OPENING THE BUILDING FACADE FOR WATER AND FREEZE THAW DAMAGE.



STEEL LINTEL IS RUST JACKING THE MASONRY, OPENING THE BUILDING FACADE FOR WATER AND FREEZE THAW DAMAGE.



STEEL LINTEL AT WINDOW IS RUST JACKING THE MASONRY, OPENING THE BUILDING FACADE FOR WATER AND FREEZE THAW DAMAGE.



FAILED MORTAR JOINTS, OPENING THE BUILDING FACADE FOR WATER AND FREEZE THAW DAMAGE.



STEEL LINTEL IS RUST JACKING THE MASONRY, OPENING THE BUILDING FACADE FOR WATER AND FREEZE THAW DAMAGE.



STEEL LINTEL IS RUST JACKING THE MASONRY, OPENING THE BUILDING FACADE FOR WATER AND FREEZE THAW DAMAGE.



FREEZE THAW FROM ABOVE DAMAGE / RUSTING OF STEEL MEMBERS. OPENING THE BUILDING FACADE FOR WATER AND FREEZE THAW DAMAGE.



POBOX 345,
BOSTON, MA. 02127.
617-334-5355
WWW.CALEDONIANCORP.COM

CHESTNUT MANOR CONDOS,
276 CHESTNUT HILL AVE,
BOSTON MA.



APPROXIMATE LOCATIONS OF EXPANSION JOINTS



POBOX 345,
BOSTON, MA, 02127.
617-334-5355
WWW.CALEDONIANCORP.COM

CHESTNUT MANOR CONDOS,
276 CHESTNUT HILL AVE,
BOSTON MA.