



Old North Church Accessibility Improvements

Landmarks Design Review

02 AUGUST 2022



EXISTING CONDITIONS - OPPORTUNITIES



BLUE STONE SEAT WALLS



GIFT SHOP ENTRANCE



PATIO



18TH CENTURY GARDEN

EXISTING CONDITIONS - CONSTRAINTS



STAIRS TO GIFT SHOP



EXPOSED UTILITIES



RAILING



SITE ENTRANCE



MAIN STAIRCASE



SITE ELEMENTS (PRESERVING CHARACTER)



DECORATIVE GATE



DECORATIVE FENCE



GRANITE TREADS



FREEDOM TRAIL



BRICK WALLS



BLUESTONE SEAT WALLS



BRICK PAVERS



EXISTING SITE PLAN




PROPOSED SITE PLAN




EXISTING SITE PLAN




PROPOSED SITE PLAN





PROPOSED SITE PLAN



BEFORE/AFTER IMAGES



BEFORE/AFTER IMAGES



RENDERED VIEW

