

82 Waltham Street – front door replacement

Exiting conditions

- Current door is made of stained **softwood** (probably pine wood), which is not standard for the South End
 - Front doors are typically made of hardwood – mahogany or oak
 - Door is most likely a **non-historically correct replacement**
- Given its soft material, the door has been **prone to damage** and has required frequent renovations

Proposed replacement


- Replace this softwood door with a mahogany door, painted in black
- Custom made by Olde Bostonian to replicate a historic design found on other buildings in the South End
 - See next page

82 Waltham Street – front door replacement

Existing conditions – pine wood door



Proposed replacement – mahogany door



Custom replica of this historic South End design, made by Olde Bostonian