

Beacon Hill Architectural Commission
Public Hearing
November 20, 2025

Application #26.0419 BH

101 Pinckney Street, Boston

Timothy Burke ARCHITECTURE




#### **Location and Context**




- Existing building constructed ca. 1840
- Existing rear garden wall likely dates to mid-20<sup>th</sup> century
- No building permit for the rear garden wall; known to be in place by 1965 and may have existed in another form previously
- Likely constructed by Leslie Hastings, owner of the property in the mid-20<sup>th</sup> century who also enclosed the west side of the yard
- Curb cut has been in place since the mid-1970s and was previously located further west
- Existing garden door installed in 2016 as approved by BHAC




101 Pinckney Street rear garden wall on Myrtle Street, view southwest



Atlas map from 1861 showing the subject property and rear yards and sheds accessed from Myrtle Street. Source: Pinney, C., Plan of the City of Boston (Boston: L. Prang & Co., 1861).



Atlas map from 1912 showing the subject property and rear yard after the construction of 132 and 136 Myrtle Street. Source: Bromley G.W. and W.S. Bromley, *Atlas of the City of Boston : Boston proper and Back Bay* (Philadelphia : G.W. Bromley & Co., 1912).




Plot plan from 1965 showing rear wall in place. Text below Myrtle Street (at right) reads "Wall (No Gate). Source: City of Boston Archives.



Detail from 1975 photograph of Myrtle Street showing curb cut in place. Source: Beacon Hill Historic District National Register Nomination, 1975.



Ca. 1993 photograph showing prior location of curb cut further west on Myrtle St, aligning with area of masonry rebuilding. Source: City of Boston Archives.



Existing conditions showing curb cut location today (October 2025).

# 101 Pinckney Street – Existing Conditions



Rear garden wall on Myrtle Street, contextual photograph, view southwest



Rear garden wall on Myrtle Street, view southwest

# 101 Pinckney Street – Existing Conditions



Rear garden wall on Myrtle Street, view southeast



Rear garden wall on Myrtle Street, area of rebuilding at west end, view east

# 101 Pinckney Street – Context



Contextual view, Myrtle Street with rear garden wall at upper left, view southeast



Contextual view, south end of Myrtle Street from east of project site, view west

#### 101 Pinckney Street – Context



Contextual view, rear garden walls and doors of 87 and 89 Pinckney Street fronting Myrtle Street east of project site, view southwest



Contextual view, rear garden walls and doors of Pinckney and West Cedar Street properties fronting Myrtle Street west of project site, view southwest

